

Western Run Pilot Project - Baltimore Maryland

Unique Test ID 263 Date: 10/7/2004 MeterBasin: 01_WR28
Observer ID: B Crew: T-2 Dye Test Recommended: N

Defect No: 4 Setup No: 2 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

3926 Fallstaff ROAD

Source Type: 04= Cleanout **Location:** 7=Yard-Front **Severity:** 4=Major

Sector: 2=Private Drainage Area: 16

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 411

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007Image0411.JPG

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

263

Filename Path:

 $X:\Baltimore\ City\Western\ Run\ Pilot\ Area-Data\ Files\Smoke\ Testing\Pictures\Sketches\263.tif$

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID 263 Date: 10/7/2004 MeterBasin: 01_WR28
Observer ID: B Crew: T-2 Dye Test Recommended: N

Defect No: 5 Setup No: 2 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

3914 Fallstaff ROAD

Source Type: 04= Cleanout **Location:** 7=Yard-Front **Severity:** 4=Major

Sector: 2=Private **Drainage Area:** 0

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 420

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007Image0420.JPG

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

263

Filename Path:

 $X:\Baltimore\ City\Western\ Run\ Pilot\ Area-Data\ Files\Smoke\ Testing\Pictures\Sketches\263.tif$

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID 263 Date: 10/7/2004 MeterBasin: 01_WR28
Observer ID: B Crew: T-2 Dye Test Recommended: N

Defect No: 6 Setup No: 2 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

3906 Fallstaff ROAD

Source Type: 04= Cleanout **Location:** 7=Yard-Front **Severity:** 3=Moderate

Sector: 2=Private **Drainage Area:** 0

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 412

Filename Path:

 $\label{eq:continuity} X\Baltimore\ City\Western\ Run\ Pilot\ Area\ -\ Data\ Files\Smoke\ Testing\Pictures\1007-2004\T-2\PLAYER_8\B_2004_1007\Image0412.JPG$

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

263

Filename Path:

 $X:\Baltimore\ City\Western\ Run\ Pilot\ Area-Data\ Files\Smoke\ Testing\Pictures\Sketches\263.tif$

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID 263 Date: 10/7/2004 MeterBasin: 01_WR28
Observer ID: B Crew: T-2 Dye Test Recommended: N

Defect No: 7 Setup No: 2 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

3904 Fallstaff ROAD

Source Type: 04= Cleanout **Location:** 7=Yard-Front **Severity:** 3=Moderate

Sector: 2=Private **Drainage Area:** 0

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 413

Filename Path:

 $X\Baltimore\ City\Western\ Run\ Pilot\ Area\ -\ Data\ Files\Smoke\ Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007\Image0413\JPG$

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

263

Filename Path:

 $X:\Baltimore\ City\Western\ Run\ Pilot\ Area-Data\ Files\Smoke\ Testing\Pictures\Sketches\263.tif$

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID 263 Date: 10/7/2004 MeterBasin:

Observer ID: B Crew: T-2 Dye Test Recommended: N

Defect No: 8 Setup No: 2 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

3810 Fallstaff ROAD

Source Type: 04= Cleanout **Location:** 7=Yard-Front **Severity:** 4=Major

Sector: 2=Private Drainage Area: 4

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 414

Filename Path:

 $X\Baltimore\ City\Western\ Run\ Pilot\ Area\ -\ Data\ Files\Smoke\ Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007Image0414.JPG$

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

263

Filename Path:

 $X.\Baltimore\ City\Western\ Run\ Pilot\ Area-Data\ Files\Smoke\ Testing\Pictures\Sketches\263.tif$

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID 263 Date: 10/7/2004 MeterBasin:

Observer ID: B Crew: T-2 Dye Test Recommended: N

Defect No: ⁹ Setup No: ² Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

3806 Fallstaff ROAD

Source Type: 04= Cleanout **Location:** 7=Yard-Front **Severity:** 4=Major

Sector: 2=Private Drainage Area: 40

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 415

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007Image0415.JPG

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

263

Filename Path:

 $X:\Baltimore\ City\Western\ Run\ Pilot\ Area-Data\ Files\Smoke\ Testing\Pictures\Sketches\263.tif$

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID 264 Date: $^{10/7/2004}$ MeterBasin: 01 _WR28 Observer ID: B Crew: $^{T-2}$ Dve Test Recommended: N

Defect No: 1 Setup No: 3 Priority CCTV:

House Number Street Prefix: Street Name: Street Type: 3801 Fallstaff ROAD

Source Type: 12= MH Frame Seal **Location:** 7=Yard-Front **Severity:** 4=Major

Sector: 1=Public Drainage Area: 16

Comments: MH 1521334

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 419

Filename Path:

 $X\Baltimore\ City\Western\ Run\ Pilot\ Area\ -\ Data\ Files\Smoke\ Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007\Image0419\JPG$

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

264

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\264.tif

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

| Unique Test ID | 264 | Date: | 10/7/2004 | MeterBasin: | 01_WR28 |
|---------------------|-----|-------|-----------|------------------------------|---------|
| Observer ID: | В | Crew: | T-2 | Dve Test Recommended: | N |

Defect No: ² Setup No: ³ Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

3829 Labyrinth ROAD

Source Type: 04= Cleanout **Location:** 7=Yard-Front **Severity:** 4=Major

Sector: 2=Private **Drainage Area:** 0

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 421

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007Image0421.JPG

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

264

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\264.tif

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

| Unique Test ID | 264 | Date: | 10/7/2004 | MeterBasin: | 01_WR28 |
|----------------|-----|------------|-----------|------------------------------|---------|
| Observer ID: | В | Crew: | T-2 | Dve Test Recommended: | N |
| Dafa at Max | 3 | Catana Nas | 3 | Dai anita CCTV. | |

Defect No: 3 Setup No: 3 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

3807 Labyrinth ROAD

Source Type: 04= Cleanout **Location:** 7=Yard-Front **Severity:** 4=Major

Sector: 2=Private **Drainage Area:** 0

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 422

Filename Path:

 $X\Baltimore\ City\Western\ Run\ Pilot\ Area\ -\ Data\ Files\Smoke\ Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007\Image0422\ JPG$

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

264

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\264.tif

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

| Unique Test ID | 264 | Date: | 10/7/2004 | MeterBasin: | 01_WR28 |
|-----------------------|-----|-------|-----------|------------------------------|---------|
| Observer ID: | В | Crew: | T-2 | Dve Test Recommended: | N |
| | | | _ | | |

Defect No: 4 Setup No: 3 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

3805 Labyrinth ROAD

Source Type: 04= Cleanout **Location:** 7=Yard-Front **Severity:** 4=Major

Sector: 2=Private **Drainage Area:** 0

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 423

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007Image0423.JPG

Image Status: Image found and displayed.

Photo No:


Filename Path:





Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

264

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\264.tif

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

| Unique Test ID | 264 | Date: | 10/7/2004 | MeterBasin: | 01_WR28 |
|---------------------|-----|-------|-----------|------------------------------|---------|
| Observer ID: | В | Crew: | T-2 | Dve Test Recommended: | N |

Defect No: 5 Setup No: 3 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

3800 Labyrinth ROAD

Source Type: 18= Other **Location:** 14=Other **Severity:** 1=No Smoke

Sector: 2=Private **Drainage Area:** 0

Comments: B5

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 424

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007Image0424.JPG

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

264

Filename Path:

 $X:\Baltimore\ City\Western\ Run\ Pilot\ Area-Data\ Files\Smoke\ Testing\Pictures\Sketches\264.tif$

Image Status: Image found and displayed.

Achieving is working logother

SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| Unique Test ID | 264 | Date: | 10/7/2004 | MeterBasin: | 01_WR28 |
|-----------------------|-----|-------|-----------|------------------------------|---------|
| Observer ID: | В | Crew: | T-2 | Dve Test Recommended: | N |
| - 4 | (| ~ | 2 | | |

Defect No: 6 Setup No: 3 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

3703 Fallstaff ROAD

Source Type: 04= Cleanout **Location:** 8=Yard-Back **Severity:** 3=Moderate

Sector: 2=Private **Drainage Area:** 0

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 425

Filename Path:

 $X\Baltimore\ City\Western\ Run\ Pilot\ Area\ -\ Data\ Files\Smoke\ Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007\Image0425\JPG$

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

264

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\264.tif

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

| Unique Test ID | 264 | Date: | 10/7/2004 | MeterBasin: | 01_WR28 |
|----------------|-----|-------|-----------|-----------------------|---------|
| Observer ID: | В | Crew: | T-2 | Dve Test Recommended: | N |

Defect No: 7 Setup No: 3 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

3703 Fallstaff ROAD

Source Type: 02= Service Line **Location:** 8=Yard-Back **Severity:** 2=Trace

Sector: 2=Private Drainage Area: 20

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 426

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007Image0426.JPG

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

264

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\264.tif

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID 265 Date: 10/7/2004 MeterBasin:

Observer ID: B Crew: T-2 Dye Test Recommended: N

Defect No: 1 Setup No: 4 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

6800 Williamson AVE

Source Type: 04= Cleanout **Location:** 7=Yard-Front **Severity:** 4=Major

Sector: 2=Private **Drainage Area:** 0

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 427

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007Image0427.JPG

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

265

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\265.tif

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Defect No: 2 Setup No: 4 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

6807 Williamson AVE

Source Type: 04= Cleanout **Location:** 7=Yard-Front **Severity:** 4=Major

Sector: 2=Private **Drainage Area:** 0

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 428

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007Image0428.JPG

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

265

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\265.tif

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID 265 Date: 10/7/2004 MeterBasin: 01_WR28
Observer ID: B Crew: T-2 Dve Test Recommended: Y

Defect No: 3 Setup No: 4 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

3700 Labyrinth ROAD

Source Type: 14= Catch Basin **Location:** 7=Yard-Front **Severity:** 4=Major

Sector: 1=Public Drainage Area: 10000

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 429

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007Image0429.JPG

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

265

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\265.tif

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

| Unique Test ID | 265 | Date: | 10/7/2004 | MeterBasin: | 01_WR28 |
|-----------------------|-----|-------|-----------|------------------------------|---------|
| Observer ID: | В | Crew: | T-2 | Dve Test Recommended: | N |
| - 4 | 4 | ~ | 4 | | |

Defect No: 4 Setup No: 4 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

3618 Labyrinth ROAD

Source Type: 04= Cleanout **Location:** 7=Yard-Front **Severity:** 3=Moderate

Sector: 2=Private **Drainage Area:** 0

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 430

Filename Path:

 $X\Baltimore\ City\Western\ Run\ Pilot\ Area\ -\ Data\ Files\Smoke\ Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007\Image0430\JPG$

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

265

Filename Path:

 $X.\Baltimore\ City\Western\ Run\ Pilot\ Area-Data\ Files\Smoke\ Testing\Pictures\Sketches\265.tif$

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Unique Test ID 265 Date: 10/7/2004 MeterBasin: 01_WR28
Observer ID: B Crew: T-2 Dye Test Recommended: N

Defect No: 5 Setup No: 4 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

3605 Labyrinth ROAD

Source Type: 04= Cleanout **Location:** 7=Yard-Front **Severity:** 3=Moderate

Sector: 2=Private **Drainage Area:** 0

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 431

Filename Path:

X\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007Image0431.JPG

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

265

Filename Path:

 $X:\Baltimore\ City\Western\ Run\ Pilot\ Area\ -\ Data\ Files\Smoke\ Testing\Pictures\Sketches\265.tif$

Image Status: Image found and displayed.

Achieving is working logother

SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID 265 Date: 10/7/2004 MeterBasin: 01_WR28
Observer ID: B Crew: T-2 Dve Test Recommended: N

Defect No: 6 Setup No: 4 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

3600 Labyrinth ROAD

Source Type: 04= Cleanout **Location:** 7=Yard-Front **Severity:** 3=Moderate

Sector: 2=Private **Drainage Area:** 0

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 432

Filename Path:

 $X\Baltimore\ City\Western\ Run\ Pilot\ Area\ -\ Data\ Files\Smoke\ Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007\Image0432\JPG$

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

265

Filename Path:

 $X.\Baltimore\ City\Western\ Run\ Pilot\ Area-Data\ Files\Smoke\ Testing\Pictures\Sketches\265.tif$

Image Status: Image found and displayed.



Western Run Pilot Project - Baltimore Maryland

Defect No: 7 Setup No: 4 Priority CCTV:

House Number Street Prefix: Street Name: Street Type:

3600 Labyrinth ROAD

Source Type: 04= Cleanout **Location:** 7=Yard-Front **Severity:** 4=Major

Sector: 2=Private **Drainage Area:** 0

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 433

Filename Path:

 $X\Baltimore\ City\Western\ Run\ Pilot\ Area\ -\ Data\ Files\Smoke\ Testing\Pictures\1007-2004\T-2\PLAYER_B\B_2004_1007\Image0433\JPG$

Image Status: Image found and displayed.


Photo No:

Filename Path:



Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

265

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\265.tif

Image Status: Image found and displayed.